



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor  
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@dhw.idaho.gov](mailto:fsb@dhw.idaho.gov)

December 5, 2013

Melissa Fustos, Administrator  
Divine Living Centers at Curry Retirement Estate  
3805 North 2538 East  
Twin Falls, ID 83301

License #: RC-924

Dear Ms. Fustos:

On October 15, 2013, a Fire Life Safety Survey was conducted at Divine Living Centers at Curry Retirement Estate. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level:

- Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Tom Mroz, Health Facility Surveyor, Facility Fire Safety and Construction Program, at (208) 334-6626.

Sincerely,

TOM MROZ  
Health Facility Surveyor  
Facility Fire Safety & Construction Program

TM/lj



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER, Governor  
RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T – Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, Idaho 83720-0009  
PHONE: (208) 334-6626  
FAX: (208) 364-1888  
E-mail: [fsb@chw.idaho.gov](mailto:fsb@chw.idaho.gov)

October 22, 2013

Melissa Fustos, Administrator  
Divine Living Centers at Curry Retirement Estate  
3805 North 2538 East  
Twin Falls, ID 83301

Dear Ms. Fustos:

On October 15, 2013, a Fire Life Safety Survey was conducted at Divine Living Centers at Curry Retirement Estate. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by November 15, 2013.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK P. GRIMES, Supervisor  
Facility Fire Safety & Construction Program

MPG/lj  
Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>13R924</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01 - ENTIRE BUILDING</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>10/15/2013</b>
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  <b>DIVINE LIVING CENTERS AT CURRY RETIREM</b>	STREET ADDRESS, CITY, STATE, ZIP CODE <b>3805 NORTH 2538 EAST TWIN FALLS, ID 83301</b>
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
--------------------	--	---------------	---	--------------------

R 000	<p>Initial Comments</p> <p>The facility was found to be in substantial compliance with the life safety code requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard life safety code survey conducted on October 15, 2015.</p> <p>The surveyor conducting the survey was:</p> <p>Tom Mroz CFI-II Health Facility Surveyor Facility Fire Safety &amp; Construction</p>	R 000		
-------	---	-------	--	--

Bureau of Facility Standards LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

